



**Consulting**



**Training**




**Customizing**

## **external NX-Tools (batchmode)**

Obrigheim, 17.11.2020

Im Luss 5 - 74847 Obrigheim - [info@ibth-consulting.de](mailto:info@ibth-consulting.de)



## massprop.exe (NXBIN Folder)

*Create new \*.bat file...*

**Content:**

**@echo off**

**D:\Siemens\1926\NXBIN\massprop.exe %1**

**Pause**

***Alternative (depends on your installation):***

**set PATH=%PATH%;%UGII\_BASE\_DIR%**

**%UGII\_BASE\_DIR%/nxbin/massprop.exe %1**



## ug\_convert\_part.exe (NXBIN Folder)

*Create new \*.bat file...*

**Content:**

**@echo off**


**D:\Siemens\1926\NXBIN\ug\_convert\_part.exe -mm %1**

**Pause**

***Alternative (depends on your installation):***

**set PATH=%PATH%;%UGII\_BASE\_DIR%**

**%UGII\_BASE\_DIR%/nxbin/ug\_convert\_part.exe -mm %1**



## Start → regedit ...

shell → right click → New Key "Massprop"


Massprop → right click New Key "command"

Massprop → right click New String Value "Icon"

Massprop → Icon → Double Click = "D:\CAD\_OOTB\03\_massprop.bat"

Massprop → Default → Double Click = 03\_massprop.bat

command → Default → Double Click = "D:\CAD\_OOTB\03\_massprop.bat" "%1"



Computer\HKEY\_CLASSES\_ROOT\\*\shell\

